

Issues and workaround in Digital Performer for TAC-Series

August, 2016

IMPORTANT NOTICE.

Zoom TAC-2, TAC-2R, and TAC-8 Thunderbolt® audio interfaces generate noise when using the following:

- Mac OS X 10.11
- Digital Performer 9.02

If this problem occurs, please try the following workaround every time when you start digital performer9.02 with TAC-Series.

Setup > Configure Audio System > Configure Hardware Driver

- Select your device (*TAC-2 or TAC-2R or TAC-8) and click OK button.

* Even if your device has been already selected, please click OK button.

We will post updated information on our website as soon as the permanent solution is ready.