

Important notice about TAC-Series and Digital Performer

July, 2016

IMPORTANT NOTICE.

Zoom TAC-2, TAC-2R, and TAC-8 Thunderbolt® audio interfaces have been found to generate noise when using the following:

- Mac OS X 10.11
- Digital Performer 9.02

We will post updated information on our website as soon as the solution is ready.